

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

70.0

47.0

6.7

2.2

7.5

1.0

N/A

Good 7.9

Intersection ID: 10011804 Main Street: MASONIC DR Cross Street: N/A Location: Ε Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10 ADA ID: 77B272A20680 Ramp Type: Combination1

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

No

Yes

No

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)

Data

72.0

48.0

4.5

1.5

24.5

48.0

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None MASONIC DR Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A Yes Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A N/A



Total Cost:



N/A

1800.00

N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A **DWS Contrast?** Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? N/A To W X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 1.8 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 1.4 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes

Surface Condition? (G/P)

Curb Slope (%)