

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

60.0

59.0

7.1

2.7

8.7

4.7

N/A

No

To N

N/A

4.1

2.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 6.2

Intersection ID: N/A Main Street: STATESVILLE_AV Cross Street: ALMA_CT Location: SW

ADA ID: 7801331A346B Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None STATESVILLE AV StopSign ALMA CT Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost:

Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 58.0 Ramp Length RT (in) 59.5 Yes Ramp Width LT (in) Yes Ramp Width RT (in) Yes Yes Ramp Slope LT (%) 5.0 Ramp Slope RT (%) Ramp XSlope LT (%) 2.7 No Ramp XSlope RT (%) No N/A Ramp Length (in) 59.0 Nο Ramp Slope (%) 43.0 No Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To E X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) X Walk 2 Slope (%) 0.2 X Walk 1 Slope (%) X Walk 1 X Slope (%) 4.8 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2?

5.0

3.1

N/A

N/A

N/A

Yes

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







Road Slope (%)

Road X Slope (%)

3200.00