



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18125	Main Street: BRANDYWINE_RD	Cross Street: CHELSEA_DR	Location: NW
ADA ID: 782389337A16	Ramp Type: BlendTrans2	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance											
 <div>Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2</div> <div>BRANDYWINE RD StopSign CHELSEA DR StopSign</div>			Possible Solutions:			Compliance			Description			Data		
			Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A			Ramp Length (in)			91.0		
Surveyor Notes:			ASP LIP 0.5			No			Ramp Width (in)			46.0		
			PROW/ADA:			N/A			Flare Type LT			N/A		
R304.5.1, R304.5.3			Total Cost:			\$			3200.00			N/A		
						N/A			Flare Slope LT (%)			N/A		
						N/A			Flare Traversable LT?			N/A		
						N/A			Landing Length (in)			N/A		
						N/A			Landing Width (in)			N/A		
						N/A			Landing Slope (%)			N/A		
						N/A			Landing X Slope (%)			N/A		
						N/A			Landing Curb? (Y/N)			N/A		
						N/A			Shared Landing?			N/A		
						N/A			Gutter Ponding?			N/A		
						N/A			Gutter Lip Ht (in)			N/A		
						N/A			Painted X Walk1?			No		
									X Walk 1 Direction			To S		
									X Walk 1 Width (in)			N/A		
									X Walk 1 Slope (%)			5.7		
									X Walk 1 X Slope (%)			3.5		
						N/A			Ramp inside XWalk1?			N/A		
									Road Slope (%)			2.6		
									Road X Slope (%)			7.7		
						N/A			Any Obstructions?			N/A		
									Obstruction Type					
												N/A		
												Yes		
												N/A		
												Curb Slope (%)		
												2.7		

Total Cost: \$ 3200.00

