

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

N/A

N/A

Good

17.3

Intersection ID: 51751 Main Street: GOLF\_LINKS\_DR Cross Street: GOLF LINKS DR N Location: NW ADA ID: 786CDFF279EB Ramp Type: Combination1Diag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 

Compliance Description

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

Data Compliance Description



Street 1 Name None **GOLF LINKS DR** Stop Condition-Street 1 Street 2 Name StopSign Stop Condition-Street 2 **GOLF LINKS DR N** 

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3



3200.00

				•	
N/A	Ramp Length LT (in)	36.0	N/A	Ramp Length RT (in)	56.0
Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0
Yes	Ramp Slope LT (%)	6.3	Yes	Ramp Slope RT (%)	6.5
Yes	Ramp XSlope LT (%)	0.5	Yes	Ramp XSlope RT (%)	0.7
N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.9
No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	5.2
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	5.4
	X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	2.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	4.8		Clear Space?	N/A
	Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
1			N/A	Any Obstruction?	N/A
				Obstruction Type	
	En I				N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)





Total Cost: