

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19934Main Street: W\_ARROWOOD\_RDCross Street: WHITEHALL\_EXECUTIVE\_CENTER\_DRLocation:NWADA ID: 786F07F235D9Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name WARROWOOD RD
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:									
Remove & Replace Entire Ramp.									
Surveyor Notes:									
·									
N/A									
PROW/ADA:									
Not Found, R304.5.1, R304.2.2,									
R304.5.3									

Total Cost:		\$	1850.00

Field Measurements/Component Compliance									
Comp	liance Description	Data	Comp	liance	Description	Data			
N/A	Ramp Length (in)	48.0	No	Ramp	Slope (%)	8.5			
No	Ramp Width (in)	46.5	No	Ramp	XSlope (%)	5.1			
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A			
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A			
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	3.4		X Wa	lk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	0.4		X Wa	lk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm	Grate/Utility Type				
		N/A				N/A			
			Yes	Surfa	ce Condition? (G/P)	Good			





