


Intersection ID: 15459		Main Street: CONISTON_PL		Cross Street: S_KINGS_DR		Location:		SE			
ADA ID: 78760AF89D08		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		73.0	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		51.0	
						Yes		Ramp Slope (%)		5.2	
PROW/ADA:				R304.5.3		No		Ramp XSlope (%)		2.3	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
						N/A		Landing Length (in)		0.0	
						N/A		Landing Width (in)		0.0	
						N/A		Landing Slope (%)		0.0	
						N/A		Landing X Slope (%)		0.0	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		0.0	
						N/A		Gutter Lip Ht (in)		0.0	
						N/A		Painted X Walk1?		No	
								X Walk 1 Direction		To NW	
						N/A		X Walk 1 Width (in)		N/A	
						N/A		X Walk 1 Slope (%)		2.0	
						N/A		X Walk 1 X Slope (%)		2.0	
						N/A		Ramp inside XWalk1?		N/A	
						N/A		Any Obstructions?		N/A	
								Obstruction Type		Yes	
						N/A		Surface Condition? (G/P)		Good	
						N/A		Curb Slope (%)		5.7	

