














Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19936	Main Street: ARCHDALE_DR	Cross Street: CHERRYCREST_LN	Location: NW
ADA ID: 788B5C6DD802	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		73.0	Yes	Ramp Slope (%)	6.4
	Surveyor Notes:		No		Ramp Width (in)		46.5	No	Ramp XSlope (%)	6.1
	N/A		N/A		Flare Type LT		N/A	N/A	Flare Type RT	N/A
	PROW/ADA:		N/A		Flare Slope LT (%)		N/A	N/A	Flare Slope RT (%)	N/A
	Not Found, R304.5.1, R304.5.3		N/A		Flare Traversable LT?		N/A	N/A	Flare Traversable RT?	N/A
	Total Cost:		N/A		Landing Length (in)		N/A	N/A	DWS Provided?	N/A
	\$ 3200.00		N/A		Landing Width (in)		N/A	N/A	DWS Contrast?	N/A
			N/A		Landing Slope (%)		N/A	N/A	DWS Length (in)	N/A
			N/A		Landing X Slope (%)		N/A	N/A	DWS Full Width?	N/A
			N/A		Landing Curb? (Y/N)		N/A	N/A	DWS Offset (in)	N/A
			N/A		Shared Landing?		N/A			
			N/A		Gutter Ponding?		N/A	N/A	Gutter Slope (%)	N/A
			N/A		Gutter Lip Ht (in)		N/A	N/A	Gutter X Slope (%)	N/A
			N/A		Painted X Walk1?		No	N/A	Painted X Walk2?	No
			N/A		X Walk 1 Direction		To S		X Walk 2 Direction	To NE
			N/A		X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)	N/A
			N/A		X Walk 1 Slope (%)		7.7		X Walk 2 Slope (%)	3.5
			N/A		X Walk 1 X Slope (%)		1.9		X Walk 2 X Slope (%)	7.0
			N/A		Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?	N/A
			N/A		Road Slope (%)		4.4	N/A	Clear Space?	N/A
			N/A		Road X Slope (%)		7.9	N/A	Clear Space to XWalk (in)	N/A
			N/A		Any Obstructions?		N/A	N/A	Storm Grate/Utility Hazard?	N/A
			N/A		Obstruction Type				Storm Grate/Utility Type	
			N/A				N/A			N/A
			N/A					Yes	Surface Condition? (G/P)	Good

