

Access Compliance Report Public Rights-of-Way (Curb Ramps)

Intersection ID: 51776 Main Street: MCVAY_ST Cross Street: ORANGE_ST Location: E

ADA ID: 78A35A4071E9 Ramp Type: Directional1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 2.75

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance



Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

PROW/ADA:
R304.5.3, R304.5.2, R305.1.4, R305.2

Street 1 Name **ORANGE ST**
Stop Condition-Street 1 **None**
Street 2 Name **N/A**
Stop Condition-Street 2 **N/A**

Total Cost: \$ **1600.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	93.0	No	Grade Break?	No
Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	7.0
Yes	Ramp Slope (%)	7.7	N/A	Grade Break XSlope (%)	5.6
No	Ramp XSlope (%)	3.3			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.3	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.9	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	28.0
N/A	Shared Landing?	Yes	No	DWS Offset RT (in)	3.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.8
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6
N/A	Painted X Walk1?	No		Road Slope (%)	2.2
	X Walk 1 Direction	To W		Road X Slope (%)	1.3
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.3	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	22.1

