

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7623	Main Street: DERRYDOWNE_DR	Cross Street: MONTEITH_DR	Location: NW
ADA ID: 78BF4FFFB9BE	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	39.5	Yes	BlendTrans Slope (%)	1.7
Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	4.0
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	3.0	N/A	Flare Slope RT (%)	0.2
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	24.5
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	0.6
N/A	Gutter Lip Ht (in)	0.3	N/A	Gutter X Slope (%)	4.3
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	7.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	2.0		Clear Space?	Yes
	Road X Slope (%)	7.1	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
		Yes		Surface Condition? (G/P)	Good
		No		Curb Slope (%)	18.5

Street 1 Name DERRYDOWNE DR

Stop Condition-Street 1 StopSign

Street 2 Name N/A

Stop Condition-Street 2 N/A

