



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9578	Main Street: WOODWARD_AV	Cross Street: STATESVILLE_AV	Location: SE
ADA ID: 78C29510D64B	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	38.0
			No	Ramp Width LT (in)	47.0
			Yes	Ramp Slope LT (%)	1.0
			Yes	Ramp XSlope LT (%)	1.1
			N/A	Ramp Length (in)	26.0
			No	Ramp Width (in)	47.5
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.5.1, R304.5.3, R304.3.2</p>			N/A	Ramp Length RT (in)	55.0
			Yes	Ramp Width RT (in)	48.0
			No	Ramp Slope RT (%)	9.7
			No	Ramp XSlope RT (%)	3.3
			Yes	Ramp Slope (%)	6.6
			No	Ramp XSlope (%)	6.4
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
<p>Total Cost:</p> <p>\$ 1800.00</p>			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk2?	N/A
			To N	X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
			1.9	X Walk 2 Slope (%)	N/A
			4.5	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	2.0