cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 8246 Ma	6 Main Street: AUGUSTA_ST		Cross Street: CATHERINE_SIMMONS_AV				NW
ADA ID: 790A4B33D36B Ra	036B Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	47.5
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance Description Data Compliance				Data	
CATHLERINE_SEMMONS_LAV	Remove & Replace Curb Ramp V	Vith N/A	Ramp Length (in)	39.0	Yes	Ramp Slope (%)	7.6
	Two New Directional Ramps or	No	Ramp Width (in)	26.0	No	Ramp XSlope (%)	5.1
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	MARCE .	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	hours	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
C. C.		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	The second se	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To S		X Walk 2 Direction	To E
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CATHERINE SIMMO	NS AV		X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	1.8
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	0.7
Street 2 Name AUGUS	TA ST	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 Sto	pSign		Road Slope (%)	1.8	N/A	Clear Space?	N/A
			Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 3	200.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A