

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MALLARD_CREEK_RD Intersection ID: 4973 Cross Street: W_W_T_HARRIS_BV Location: ADA ID: 7921AA5B70E9 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	W W T HARRIS BV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost:	\$	1850.0

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	oliance Description	Data			
N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	9.2			
No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	2.5			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
W 186	and the second							





