

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

4.7

2.7

N/A

N/A

N/A

N/A

2.3

Good

Intersection ID: 14400Main Street:BERKELEY_AVCross Street:DILWORTH_RDLocation:NEADA ID: 794532B5C9E1Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A N/A

Curb Slope (%)



Street 1 Name

DILWORTH AV
Stop Condition-Street 1

Street 2 Name

N/A
Stop Condition-Street 2

N/A

Possible Solutions:			Compliance Description		Data	Compliance Description	
Remove & Replace Entire	e Ram	ıp.	N/A	Ramp Length (in)	33.0	N/A	Grade Break?
·		•	Yes	Ramp Width (in)	65.0	N/A	Grade Break Slope (%)
			Yes	Ramp Slope (%)	5.7	N/A	Grade Break XSlope (%)
			No	Ramp XSlope (%)	7.9		
			N/A	Flare Type LT	N/A	N/A	Flare Type RT
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)
R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)
			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)
			N/A	Painted X Walk1?	No		Road Slope (%)
				X Walk 1 Direction	To W		Road X Slope (%)
				X Walk 1 Width (in)	N/A		Clear Space?
				X Walk 1 Slope (%)	4.7	N/A	Clear Space to XWalk (in)
				X Walk 1 X Slope (%)	2.7	N/A	Storm Grate/Utility Hazard?
			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type
			N/A	Any Obstructions?	N/A		
Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)





