

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

53.0

48.0

10.3

0.6

5.2

0.2

N/A

No

To S

N/A

1.7

6.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 11.2

**Obstruction Type** 

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Yes

Intersection ID: 18196 Main Street: E WOODLAWN RD **Cross Street: WATERBURY DR** NE Location: **Overall Compliance: No Severity Score:** 0 **ADA ID: 79464ACE83FC** Ramp Type: Combination1Diag Initial Pass/Fail: Fail

## **Codes/Mitigation Info/Possible Solution**

None

## Field Measurements/Component Compliance



StopSign Street 1 Name Stop Condition-Street 1 WATERBURY DR Street 2 Name Stop Condition-Street 2 E WOODLAWN RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: ASP LIP 2.0 PROW/ADA: Not Found, R304.5.1, R304.3.2

Total Cost: 3200.00

Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 60.0 Ramp Length RT (in) 48.0 Yes Ramp Width LT (in) Yes Ramp Width RT (in) No Yes Ramp Slope LT (%) 6.1 Ramp Slope RT (%) Ramp XSlope LT (%) 0.7 Yes Ramp XSlope RT (%) Yes N/A Ramp Length (in) 48.0 Yes Ramp Slope (%) 36.0 Yes Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To W X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 8.0 X Walk 1 Slope (%) X Walk 2 Slope (%) 2.5 X Walk 1 X Slope (%) X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? Road Slope (%) 1.5 Clear Space? Road X Slope (%) 8.4 N/A Clear Space to XWalk (in) N/A Any Obstruction?





