## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: YORK_CENTER		Cross Street: N/A			Location:	NE		
ADA ID: 794BD5BBD206 Ramp Type: PerpDiag		Initial Pass/	nitial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	0.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp W	ith N/A	Ramp Length (in)	61.0	Yes	Ramp Slope (%)	5.9	
	Two New Directional Ramps or	Yes	Ramp Width (in)	59.0	No	Ramp XSlope (%)	3.5	
	Equivalent. Remove & Replace Gutter.	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	9.2	N/A	Flare Slope RT (%)	3.7	
		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
		Yes	Landing Length (in)	58.0	Yes	DWS Provided?	Yes	
	Surveyor Notes:	Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes	
	N/A	Yes	Landing Slope (%)	1.8	Yes	DWS Length (in)	24.0	
		No	Landing X Slope (%)	2.3	Yes	DWS Full Width?	Yes	
		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	2.5	
		N/A	Shared Landing?	No				
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7	
	Not Found, R304.5.3, R305.2	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.7	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To W		X Walk 2 Direction	To S	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name SANDY PORTER RD	-		X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	0.3	
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	0.6	
Street 2 Name SHUTTERFLY RD		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSign			Road Slope (%)	0.6	N/A	Clear Space?	Yes	
· · · · ·			Road X Slope (%)	5.3	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Total Cost: \$ 39	50.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

