

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.6

0.9

N/A

No

N/A

2.5

1.6

N/A

N/A

N/A

N/A

N/A

Good

To NE

Intersection ID: N/A Main Street: ARDREY KELL DR Cross Street: N/A Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 79FFDE00C8BE Ramp Type: PerpDiag Severity Score: 21.25

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

80.0

38.0

N/A

No

N/A

5.4

1.1

N/A

1.8

4.6 N/A

N/A

To SE



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

ARDREY KELL RD None **ENTRANCE** StopSign

N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** R304.5.1, R304.2.2 N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions? Total Cost: **Obstruction Type** 3200.00





