


Intersection ID: 4199		Main Street: OLD_STATESVILLE_RD		Cross Street: W_W_T_HARRIS_BV		Location:		SE											
ADA ID: 7A8EA1205540		Ramp Type: Perp		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
 <div>Street 1 Name<div>W W T HARRIS BV</div></div> <div>Stop Condition-Street 2<div>Signal</div></div> <div>Street 2 Name<div>N/A</div></div> <div>Stop Condition-Street 1<div>N/A</div></div>				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		59.0		No		Ramp Slope (%)		11.1			
						Yes		Ramp Width (in)		48.0		Yes		Ramp XSlope (%)		1.0			
						N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A			
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A			
						N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A			
						N/A		Landing Length (in)		N/A		N/A		DWS Provided?		N/A			
						N/A		Landing Width (in)		N/A		N/A		DWS Contrast?		N/A			
						N/A		Landing Slope (%)		N/A		N/A		DWS Length (in)		N/A			
						N/A		Landing X Slope (%)		N/A		N/A		DWS Full Width?		N/A			
<div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>Not Found, R304.2.2</div>				N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset (in)		N/A					
				N/A		Shared Landing?		N/A											
				N/A		Gutter Ponding?		N/A		N/A		Gutter Slope (%)		N/A					
				N/A		Gutter Lip Ht (in)		N/A		N/A		Gutter X Slope (%)		N/A					
				N/A		Painted X Walk1?		Yes		N/A		Painted X Walk2?		N/A					
						X Walk 1 Direction		To N				X Walk 2 Direction		N/A					
				N/A		X Walk 1 Width (in)		98.0		N/A		X Walk 2 Width (in)		N/A					
						X Walk 1 Slope (%)		2.4				X Walk 2 Slope (%)		N/A					
						X Walk 1 X Slope (%)		0.3				X Walk 2 X Slope (%)		N/A					
				N/A		Ramp inside XWalk1?		Yes		N/A		Ramp inside XWalk2?		N/A					
<div>Total Cost:</div> <div>\$ 1850.00</div>				Road Slope (%)		N/A		N/A		Clear Space?		N/A							
				Road X Slope (%)		N/A		N/A		Clear Space to XWalk (in)		N/A							
				N/A		Any Obstructions?		N/A		N/A		Storm Grate/Utility Hazard?		N/A					
						Obstruction Type						Storm Grate/Utility Type							
								N/A						N/A					
								Yes		Surface Condition? (G/P)		Good							

