

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5433	Main Street: PLEASANT GROVE RD	Cross Street: OLD PLANK RD	Location: W
ADA ID: 7B1B67C8C4A7	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 2.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R305.1.4, R305.2

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	82.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	58.0	Yes	Grade Break Slope (%)	1.2
Yes	Ramp Slope (%)	0.3	Yes	Grade Break XSlope (%)	0.2
Yes	Ramp XSlope (%)	1.3			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	57.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.7	Yes	DWS Length (in)	24.0
No	Landing X Slope (%)	4.1	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	8.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	24.5
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.7
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.0
N/A	Painted X Walk1?	No		Road Slope (%)	3.3
	X Walk 1 Direction	To SE		Road X Slope (%)	0.3
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.3	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	0.1

Total Cost: \$ 1600.00

