cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 15706	ntersection ID: 15796 Main Street: SNOW LN			Street		Location:	NE		
				Cross Street: IDLEWILD_RD_NORTH					
ADA ID: 7B4778A688CD Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A Contraction of the second		Possible Solutions:		Compliance Description Data Com			Comp	npliance Description Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	11.9
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	0.2
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E B				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
800 - 3				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
NOW UN S. S.		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
B B		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Star Str	THE REAL PROPERTY OF			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Cita Cita			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	KUN ES			N/A	Shared Landing?	N/A			
Att 1 Martin	Barrie Ba	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
122 1 10.11	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
	and filling			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	IDLEWILD RD NORTH	_			X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	2.3
Street 2 Name	SUTTER CREEK LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.1	N/A	Clear Space?	N/A
					Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

