


Intersection ID: 53418	Main Street: ARDREY_KELL_RD	Cross Street: SOUTHGROVE_ST	Location:	NW
ADA ID: 7B4CB20B6BE8	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:							
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>							
	Surveyor Notes:							
	<b>N/A</b>							
	PROW/ADA:							
	<b>Not Found, R304.2.2, R304.5.3</b>							
Street 1 Name	SOUTHGROVE ST		Compliance	Description	Data	Compliance	Description	Data
Stop Condition-Street 2	None		N/A	Ramp Length (in)	94.0	No	Ramp Slope (%)	9.1
Street 2 Name	ARDREY KELL RD		Yes	Ramp Width (in)	61.0	No	Ramp XSlope (%)	2.6
Stop Condition-Street 1	None		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To S		X Walk 2 Direction	To E
			N/A	X Walk 1 Width (in)	70.0	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	1.3
				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.9
			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	0.5	N/A	Clear Space?	N/A
				Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
				Obstruction Type			Storm Grate/Utility Type	
Total Cost:	\$ 3200.00				N/A			N/A
						Yes	Surface Condition? (G/P)	Good

