

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29959	Main Str	Main Street: STATESVILLE_RD			treet:	SMITH_CORNERS_B	Location:	SE			
ADA ID: 7B52677C38D3	Ramp Ty	amp Type: Perp			Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	0.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	23 12	Possible Solutions:			Compliance Description			Data Compliance Description			
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	E E	Remove & Replace E	ntire Ramp		N/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	6.5	
				-	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.6	
					N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	6.4		Flare Slope RT (%)	7.5	
6	and the second s				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
SMITH_CORNERS_EV				Yes	Landing Length (in)	60.0		DWS Provided?	Yes		
	- P	Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
	N/A			No	Landing Slope (%)	3.5	Yes	DWS Length (in)	24.0		
				Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes		
				N/A	Landing Curb? (Y/N)		No	DWS Offset (in)	4.0		
				N/A	Shared Landing?	No		2110 011001 (11)			
	PROW/ADA:			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.3		
A	R304.5.3, R304.2.2-Perp, R304.3.2		2	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.1		
	Para, R305.2	erp, R304.3	.2-	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	Fara, 1303.2			N/A	X Walk 1 Direction	To W	N/A	X Walk 2 Direction	N/A N/A		
				N/A			N/A				
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	STATESVILLE RD					X Walk 1 Slope (%)	6.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

