cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 17613 | Main Str | Cross Street: GREENWICH_RD | | | | | Location: | SW | |
|-------------------------|---|--|------------------|------------------------|-----------------------|-----------------------------|-----------|-----------------------------|-------|
| ADA ID: 7B59CEE9020D | Ramp Type: PerpDiag | | | | | | | o Severity Score: | 33.75 |
| Cod | Field Measurements/Component Compliance | | | | | | | | |
| CREATURE LEB | S CONTRACTOR | Possible Solutions: | | Compliance Description | | Data Compliance Description | | | Data |
| | | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | ith ^I | N/A | Ramp Length (in) | 69.0 | No | Ramp Slope (%) | 10.6 |
| | | | | No | Ramp Width (in) | 47.0 | No | Ramp XSlope (%) | 6.4 |
| | | | r | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | I | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | 1 | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | 1 | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | 1 | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | 1 | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | ζ, | |
| 1 18 6 1 14 | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, R304.5.1, R304.2.2, R304.5.3 | 1 | I/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | | 1 | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | No |
| | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| | | | | N/A | X Walk 1 Width (in) | 101.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | COLWICK RD | | | | X Walk 1 Slope (%) | 7.1 | | X Walk 2 Slope (%) | 0.1 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 3.0 | | X Walk 2 X Slope (%) | 2.0 |
| Street 2 Name | GREENWICH RD | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 3.3 | N/A | Clear Space? | N/A |
| 1 - | | | | | Road X Slope (%) | 2.7 | N/A | Clear Space to XWalk (in) | N/A |
| | | | 1 | A/A | Any Obstructions? | N/A | | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ 320 | 00.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | • | | | <i></i> | N/A | | | N/A |
| | | | | | | | Yes | Surface Condition? (G/P) | Good |

