

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 14515	Main Street: QUEENS_RD	Cross Street: S_CASWELL_RD	Location: S
ADA ID: 7B6D5DA385D8	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	66.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	8.2
				X Walk 1 X Slope (%)	3.7
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	2.6
				Road X Slope (%)	0.7
			N/A	Any Obstructions?	N/A
Total Cost: \$ 3200.00				X Walk 2 Direction	To NW
			N/A	X Walk 2 Width (in)	N/A
				X Walk 2 Slope (%)	0.2
				X Walk 2 X Slope (%)	2.8
			N/A	Ramp inside XWalk2?	N/A
				Clear Space?	N/A
				Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A		N/A
Stop Sign None				Surface Condition? (G/P)	Good

