cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7770	Main Street: E_ARROWHEAD_DR				Cross Street: N_TRYON_ST				Location:	NE	
ADA ID: 7C14874CFA58	Ramp Ty	Type: Combination1			Initial Pass/Fail: Pass Overall Complian			nce: No Severity Score: 20.25		20.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	1	Possible Solutions:		Compliance Description		Data Compliance Description			Data		
		Remove & Replace Entire Ramp. Remove & Replace Gutter.			N/A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	48.0	
115					Yes	Ramp Width LT (in)	73.0	Yes	Ramp Width RT (in)	72.0	
					Yes	Ramp Slope LT (%)	6.4	Yes	Ramp Slope RT (%)	3.5	
	and the same				Yes	Ramp XSlope LT (%)	1.3	Yes	Ramp XSlope RT (%)	1.9	
					N/A	Ramp Length (in)	94.0	Yes	Ramp Slope (%)	3.6	
	he deryment the second				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.1	
& TITLE SI A		Surveyor Notes:			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
		GTR LIP 1.0", RT RP < 5%			N/A	Flare Slope LT (%)	8.2	N/A	Flare Slope RT (%)	3.6	
		,			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
E ARROWHE					Yes	Landing Length (in)	72.0	Yes	DWS Provided?	Yes	
	DR 1				Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
		PROW/ADA:			Yes	Landing Slope (%)	1.9	Yes	DWS Length (in)	24.0	
L L L	and part over	Not Found, R304.5.3, R302.7.2,			No	Landing X Slope (%)	3.3	Yes	DWS Full Width?	Yes	
	inter the second second	R304.5.4			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
	0-10				N/A	Shared Landing?	No				
	- and the				Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.4	
Street 1 Name	Signal				No	Gutter Lip Ht (in)	1.0	No	Gutter X Slope (%)	2.1	
Stop Condition-Street 1	N TRYON ST				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	120.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 25	50.00	Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	Yes	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			A Received the					Yes	Any Obstruction?	No	
		a the second second		E					Obstruction Type		
					-					N/A	
								Yes	Storm Grate/Utility Hazard?	No	
						and the second s			Storm Grate/Utility Type		

Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 8.4





