

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Curb Slope (%)

14.5

Main Street: BROWNE'S_FERRY_RD Cross Street: NEUHOFF_LN Location: Intersection ID: 4052

ADA ID: 7C1591061100	DA ID: 7C1591061100 Ramp Type: Directional1			Pass/F	ail: Fail Overall (Complian	ce: N	o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data	Comp	liance Description	Data	
		Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	45.0	N/A	Grade Break?	N/A	
		·	-	No	Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0	
				Yes	Ramp Slope (%)	6.3	N/A	Grade Break XSlope (%)	0.0	
\\				Yes	Ramp XSlope (%)	1.8				
The state of the s	/	1		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
1				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
E SOUTH SEE		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
\ <u>6</u>	353 A	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
E. Carlotte				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
33000				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.1		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	0.5	
Street 1 Name	NEUHOFF LN				X Walk 1 Direction	To SW		Road X Slope (%)	3.6	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A	l	Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.6	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	





