cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43370 Main S	treet: SIMONTON_DR	Cross St	reet:	SOBECK_LN			Location:	Е
ADA ID: 7C1B7F33AEEA Ramp Type: PerpDiag		Initial Pas	itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	<u>(</u>	Compliance Description		Data Compliance Description		Data	
	Remove & Replace Curb Ramp W	∕ith [▶]	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.7
	Two New Directional Ramps or	١	/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.4
	Equivalent.	Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1	١	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	tr	1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		1	N/A	Shared Landing?	N/A			
	PROW/ADA:	1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NW		X Walk 2 Direction	To SE
		1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SOBECK LN				X Walk 1 Slope (%)	7.7		X Walk 2 Slope (%)	2.6
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	6.2
Street 2 Name SIMONTON DR		1	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	4.9	N/A	Clear Space?	N/A
				Road X Slope (%)	5.9	N/A	Clear Space to XWalk (in)	N/A
		1	A/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

