


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31292	Main Street: DEERTON_RD	Cross Street: MUNSING_DR	Location:	N
ADA ID: 7C39DA0128E5	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 10

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	46.0
			No	Ramp Width (in)	38.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
<p>Surveyor Notes:</p> <p>N/A</p>			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	N/A
			To W	X Walk 2 Direction	To S
			N/A	X Walk 2 Width (in)	N/A
			4.1	X Walk 2 Slope (%)	0.1
			2.9	X Walk 2 X Slope (%)	2.3
<p>PROW/ADA:</p> <p>R304.5.1, R304.5.3</p>			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			3.5	Clear Space to XWalk (in)	N/A
			2.9	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition? (G/P)	Good
Total Cost:		\$ 3200.00			

