

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

8.1

9.8

N/A

No

N/A

3.1

4.1

N/A

N/A

To SE

Intersection ID: 12619 Main Street: ALICE E ORR DR Cross Street: SHAMROCK DR Location: Ν **Overall Compliance: No Severity Score:** 0 ADA ID: 7C7310E95A44 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

45.0

60.5

9.6

2.5

47.0

46.0

N/A

No

N/A

1.2

2.8

N/A

4.4

To SW



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

None SHAMROCK DR StopSign **ENTRANCE** Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:





N/A

Ramp inside XWalk1?

Road Slope (%)

3200.00

Road X Slope (%) 1.9 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 7.8 Curb Slope (%)



