

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51212	Main Str	eet: PROVIDENCE_ROW_LN	1	Cross	Stroot	ARDREY_KELL_RD			Location:	NW	
			N								
ADA ID: 7C7CAEF48105 Ramp Type: Perp				Initial	Pass/Fa	ail: Fail Overall (o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Contraction of the Participation	ENC	Possible Solutions:			Comp	liance Description	Data Compliance Description			Data	
		Remove & Replace Entire	Ram	Э.	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	8.6	
			-		Yes	Ramp Width (in)	55.0	Yes	Ramp XSlope (%)	0.1	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	B A				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
157 3111					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	Bitte -				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Martin State		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
t.	6. A	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	CO B F				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	LED 2 1				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
AND DEFINER					N/A	Shared Landing?	N/A				
- Caller F	E Bund	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	6. 2	R304.2.2			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	THE LAN E				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
FAIRIN	N NOUS					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	SANDY ROCK PL					X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	