

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			·		• /						
Intersection ID: 53962 Main Street: LILAC_TREE_AV			Cros	Cross Street: DENBUR_DR				Location:	Е		
ADA ID: 7CA5CDD417F6	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	- Will March	Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data	
	3-12 May	Remove & Replace Er	tire Rar	np.	N/A	Ramp Length LT (in)	72.0	N/A	Ramp Length RT (in)	78.0	
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	A State				Yes	Ramp Width LT (in)	59.0	N/A	Ramp Width RT (in)	60.0	
	100				No	Ramp Slope LT (%)	8.5	N/A	Ramp Slope RT (%)	3.5	
1 PERSON AND A PER					No	Ramp XSlope LT (%)	2.5	N/A	Ramp XSlope RT (%)	2.2	
the second second	C.C.				N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	3.6	
い で 長					Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.9	
L. J		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N. S. Y	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
(B)	1/200				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
STATE C	and the				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	The second	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
During 1	a second	Not Found, R304.3.2, I	R304.5.3	3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
1	Marine 1	, ,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
112.	Will a la si				N/A	Shared Landing?	N/A				
Aller March	111 Martin				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	DENBUR DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			A Service					N/A	Any Obstruction?	N/A	
						Contraction of the state of the			Obstruction Type		
					100 mil 200 200 mm					N/A	
		and the second sec	CALLER THE CALLER OF CALLER	T		1411 A 1917		NI/A	Starm Crate/Utility/Uszard2		

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	24.4

