


## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 24374 Main Street: BEVERLY CREST BV Cross Street: HUGH FOREST RD Location:

ADA ID: 7D07192B3A5D Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 PINEVILLE-MATTHEWS RD Signal **HUGH FOREST RD** Signal

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or **Equivalent. Restripe Crosswalk.** Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3400.00

	Field Measurements/Component Compliance	
Compliance Description Data Compliance Description	Data	
N/A Ramp Length (in) 86.0 No Ramp Slope (%)	9.0	
No Ramp Width (in) 44.0 Yes Ramp XSlope (%)	0.4	
N/A Flare Type LT N/A N/A Flare Type RT	N/A	
N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%)	N/A	
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A	
N/A Landing Length (in) N/A N/A DWS Provided?	N/A	
N/A Landing Width (in) N/A N/A DWS Contrast?	N/A	
N/A Landing Slope (%) N/A N/A DWS Length (in)	N/A	
N/A Landing X Slope (%) N/A N/A DWS Full Width?	N/A	
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A	
N/A Shared Landing? N/A		
N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A	
N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A	
N/A Painted X Walk1? Yes N/A Painted X Walk2?	Yes	
X Walk 1 Direction To N X Walk 2 Direction	To SW	
N/A X Walk 1 Width (in) 98.0 N/A X Walk 2 Width (in)	98.0	
X Walk 1 Slope (%) 1.8 X Walk 2 Slope (%)	1.2	
X Walk 1 X Slope (%) 1.4 X Walk 2 X Slope (%)	1.0	
N/A Ramp inside XWalk1? Yes N/A Ramp inside XWalk2?	No	
Road Slope (%) 0.5 N/A Clear Space?	N/A	
Road X Slope (%) 0.9 N/A Clear Space to XWalk (	(in) <b>N/A</b>	
N/A Any Obstructions? N/A N/A Storm Grate/Utility Haz	ard? N/A	
Obstruction Type Storm Grate/Utility Type	е	
N/A	N/A	
Yes Surface Condition? (G/	P) Good	





