

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-							
Intersection ID: 52449	Main Street: TRANQUIL_OAK_PL			Cross Street: PAT_GARRETT_ST				Location:	NW
ADA ID: 7D0B3E1E376E	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
br har a		Remove & Replace Entire Ran	מו.	N/A	Ramp Length (in)	68.0	N/A	Grade Break?	N/A
			•	Yes	Ramp Width (in)	67.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	5.3	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	2.1			
A Real Property and and				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
a state a state of the				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
and the second second		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
PAT_GARRETT_ST				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
6	6. The second second			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	9			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	2.1
Street 1 Name	TRANQUIL OAK PL				X Walk 1 Direction	To E		Road X Slope (%)	0.9
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	0.3

