


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12268		Main Street: BELLE_TERRE_AV		Cross Street: THE_PLAZA		Location: NW													
ADA ID: 7D3460C3EF1C		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		78.0		N/A		Grade Break?		N/A		N/A	
						Yes		Ramp Width (in)		48.5		N/A		Grade Break Slope (%)		N/A		0.0	
						No		Ramp Slope (%)		9.2		N/A		Grade Break XSlope (%)		N/A		0.0	
						Yes		Ramp XSlope (%)		1.9									
						N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A		N/A	
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A		0.0	
						N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A		N/A	
						N/A		Landing Length (in)		0.0		N/A		DWS Provided?		N/A		N/A	
						N/A		Landing Width (in)		0.0		N/A		DWS Contrast?		N/A		N/A	
Surveyor Notes: N/A						N/A		Landing Slope (%)		0.0		N/A		DWS Length (in)		N/A			
						N/A		Landing X Slope (%)		0.0		N/A		DWS Full Width?		N/A			
						N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset LT (in)		N/A			
						N/A		Shared Landing?		N/A		N/A		DWS Offset RT (in)		N/A			
						N/A		Gutter Ponding?		0.0		N/A		Gutter Slope (%)		N/A			
						N/A		Gutter Lip Ht (in)		1.0		N/A		Gutter X Slope (%)		N/A			
						N/A		Painted X Walk1?		No				Road Slope (%)		1.0			
								X Walk 1 Direction		To S				Road X Slope (%)		0.9			
								X Walk 1 Width (in)		N/A				Clear Space?		N/A			
								X Walk 1 Slope (%)		1.0		N/A		Clear Space to XWalk (in)		N/A			
PROW/ADA: R304.2.2						N/A		X Walk 1 X Slope (%)		0.9		N/A		Storm Grate/Utility Hazard?		N/A			
						N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type					
						N/A		Any Obstructions?		N/A						N/A			
								Obstruction Type				Yes		Surface Condition? (G/P)		Good			
										N/A		N/A		Curb Slope (%)		8.3			
</																			

