cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30460 Main Street: CRESCENT_EXECUTIVE_DR C					oss Street: ARROWOOD_RD				NW
ADA ID: 7D820879865F Ramp Type: PerpDiag I				itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
a contraction		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	108.0	Yes	Ramp Slope (%)	6.7
		Two New Directional Ramps or		Yes	Ramp Width (in)	56.0	No	Ramp XSlope (%)	6.3
		Equivalent. Restripe Crosswalk.	ζ.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A AREA CARA				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Dr.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ARRON				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A		ζ, γ		
	A AN	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
S Har I I a		R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the state of the s	81	Recencie		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
en 🕈 🔥 📜					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	BI - DA			N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	108.0
Street 1 Name	ARROWOOD RD	-			X Walk 1 Slope (%)	8.2		X Walk 2 Slope (%)	1.0
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	4.9
Street 2 Name	CRESENT EXECUTIVE DR			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	No
Stop Condition-Street 1	Signal				Road Slope (%)	4.2	N/A	Clear Space?	N/A
	· ·				Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3400.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

