

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15389 Main Street: E\_INDEPENDENCE\_BV Cross Street: WILSHIRE\_PL Location: N

ADA ID: 7D94EF4EFDE3 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name E INDEPENDENCE BV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost: \$ 1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	86.0	No	Ramp	Slope (%)	8.4
No	Ramp Width (in)	45.5	Yes	Ramp	XSlope (%)	0.2
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A
	X Walk 1 Direction	To SE		X Wal	k 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.8		X Wal	k 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.7		X Wal	k 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





