

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 7065	Main Street: EBARA_LN	Cross Street: KINGVILLE_DR	Location: NE
ADA ID: 7DBE6549819F	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 8.75			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description	Data	Compliance	Description	Data
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		N/A	Ramp Length (in)	55.0	Yes	BlendTrans Slope (%)	4.0	
			No	Ramp Width (in)	47.5	Yes	BlendTrans XSlope (%)	0.0	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
PROW/ADA:		Not Found, R304.5.1	N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A	
				X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	N/A	
Street 1 Name		EBARA LN	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1		StopSign		Road Slope (%)	6.7		Clear Space?	N/A	
Street 2 Name		N/A		Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2		N/A	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
				Obstruction Type			Storm Grate/Utility Type		
						N/A		N/A	
						Yes	Surface Condition? (G/P)	Good	
						No	Curb Slope (%)	9.0	

