

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10033360	Main Street: OLD_ARDREY_KELL_RD	Cross Street: N/A	Location: SE
ADA ID: 7DC165ADD54D	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	55.0	Yes	BlendTrans Slope (%)	3.8
		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.2
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To N		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3</p>			Road Slope (%)	1.6		Clear Space?	N/A
			Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
Total Cost:					N/A	Storm Grate/Utility Hazard?	N/A
						Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good
					N/A	Curb Slope (%)	N/A

