

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.7

4.4

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 22317 Main Street: SHARON_RD Cross Street: N/A Location: W

ADA ID: 7DD0290796A6 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Flare Traversable RT?

Data

30.0

37.0

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
SHARON ACRES RD
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Not Found, R304.5.1, R304.5.3

N/A

N/A

N/A

N/A

N/A

N/A

Total Cost:

\$ 1850.00





