

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: ROCKY_RIVER_RD Cross Street: JOHN_RUSSELL_RD Location: SE ADA ID: 7DD6320E7335 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



JOHN RUSSELL RD Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 1850.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Description	Data
	N/A	Ramp Length (in)	94.0	No	Ramp	Slope (%)	8.8
	No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	1.4
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	Yes	N/A	Painte	ed X Walk2?	N/A
		X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A
	N/A	X Walk 1 Width (in)	107.0	N/A	X Wa	lk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.9		X Wa	lk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	2.7		X Wa	lk 2 X Slope (%)	N/A
	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	N/A	N/A	Clear	Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good





