## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Str	eet: HICKORY_GROVE_RD	Cross	ss Street: MARTHA'S_RIDGE_DR				Location:	SW
ADA ID: 7E1589449CF2	Ramp Ty	Ramp Type: Combination2Diag Ini			ail: Fail Overall C	ice: N	o Severity Score:	0	
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
LUCKORY_GROVE_RD		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length LT (in)	54.0	N/A	Ramp Length RT (in)	54.5
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.5
				Yes	Ramp Slope LT (%)	1.4	Yes	Ramp Slope RT (%)	5.1
				No	Ramp XSlope LT (%)	2.3	Yes	Ramp XSlope RT (%)	1.0
				N/A	Ramp Length (in)	41.5	Yes	Ramp Slope (%)	6.1
		4		No	Ramp Width (in)	40.5	Yes	Ramp XSlope (%)	1.1
		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		R304.5.1, R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	P 200 Min Line 1	1		N/A	Shared Landing?	N/A			
	The second second			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	MARTHA'S RIDGE DR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None				X Walk 1 Direction	To E		X Walk 2 Direction	To N
Stop Condition-Street 2	HICKORY GROVE RD				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	4.7
					X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	0.0
		Total Cost: \$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	1.4		Clear Space?	N/A
					Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
						N/A	Any Obstruction?	N/A	
	the second of the second second		- /					Obstruction Type	

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
   Surface Condition? (G/P)
   Good

   Curb Slope (%)
   4.4



