

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13864	Main Street: E_3RD_ST		Cross	Cross Street: 3RD-4TH_CONNECTOR_ST				Location: E	
ADA ID: 7E4012A3651	A3651D Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A 10	Mart Mart Stall	Possible Solutions:		Compliance Description Data					
Stores and a second		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	64.0	No	Ramp Slope (%)	11.4
		Two New Directional Ramps or		No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)	2.0
Con the second sec		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
S S	11 - Carrier			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A to the	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E C	A CALL YOUN	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
AND REAL	NO 12 (ALC)			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A SUL BOA				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
6.5.	190 3	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	118.0
Street 1 Name	CHARLOTTETOWNE AV	_			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	1.8
Street 2 Name	E 3RD ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	2.8	N/A	Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

