



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 6739	Main Street: CARRIAGE_OAKS_DR	Cross Street: N/A	Location: W
ADA ID: 7F08830FD109	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	47.5
			Yes	Ramp Width LT (in)	57.0
			Yes	Ramp Slope LT (%)	2.8
			No	Ramp XSlope LT (%)	5.0
			N/A	Ramp Length (in)	48.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.2.2, R304.5.3, R304.3.2</p>			N/A	Ramp Slope RT (%)	9.2
			No	Ramp XSlope RT (%)	7.1
			No	Ramp Slope (%)	10.1
			Yes	Ramp XSlope (%)	2.8
			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SE
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	3.2
				X Walk 1 X Slope (%)	4.2
			N/A	Ramp inside XWalk1?	N/A
<p>Total Cost:</p> <p>\$ 1800.00</p>			N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	N/A