cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10038458	ntersection ID: 10038458 Main Street: SOUTHERN_PINE_BV Cross Street: N/A							Location:	S
ADA ID: 7F0E8745C0F6 Ramp Type: PerpDiag			Initial I	itial Pass/Fail: Fail Overall Compliance: No				Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
THE EV		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
COUTHERN_PINES		Remove & Replace Curb Ramp \	Nith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	13.4
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second s			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	NEEV	N		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SOUTHERN_PINE				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Sourisiance		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E.	1. St.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
a for the for the second	Yest			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Attack I I I Land	4/1/			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A AND H			N/A	Shared Landing?	N/A			
A. PROMA	and interest	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	0.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	0.9
Street 2 Name	Southern Pine			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.4	N/A	Clear Space?	N/A
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

