

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.8

1.3

N/A N/A N/A N/A

N/A N/A

N/A N/A

N/A

N/A Yes To SE 112.0

1.0

1.7

Yes

N/A N/A N/A

N/A

Good

Surface Condition? (G/P)

Main Street: STEELE CREEK RD Cross Street: WALKER BRANCH DR Location: Intersection ID: 48863 NW Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 ADA ID: 7F1895FD4219

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description



Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

STEELECROFT PY Signal STEELE CREEK RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

PROW/ADA:

N/A

Not Found, R304.2.2

Street 1 Name Signal

001111	manoo Boodinphon	Dutu	001111	manoo Booonpaon
N/A	Ramp Length (in)	88.0	No	Ramp Slope (%)
Yes	Ramp Width (in)	182.0	Yes	Ramp XSlope (%)
N/A	Flare Type LT	N/A	N/A	Flare Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS Provided?
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
N/A	Shared Landing?	N/A		
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?
	X Walk 1 Direction	To SW		X Walk 2 Direction
N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)
	X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?
	Road Slope (%)	0.8	N/A	Clear Space?
	Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
	Obstruction Type		l	Storm Grate/Utility Type





Total Cost:



3200.00