

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15676Main Street: CHEROKEE\_PLCross Street: CHEROKEE\_RDLocation:NWADA ID: 7F738DE25DD9Ramp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

MIDDLETON DR StopSign CHEROKEE RD StopSign

Possible Solutions:	Co			
Remove & Replace Curb Ramp With Two New Directional Ramps or				
	N/A			
	N/A			
	N/A			
Surveyor Notes:	N/A			
N/A	N/A			
	N/A			
	N/A			
	N/A			
PROW/ADA:	N/A			
Not Found, R304.2.2	N/A			

Total Cost: \$ 3200.00

	rieiu ivieasui e	inents/C	ompo	nent Comphance	
Comp	Compliance Description		Compliance Description		Data
N/A	Ramp Length (in)	75.0	No	Ramp Slope (%)	13.1
Yes	Ramp Width (in)	50.0	Yes	Ramp XSlope (%)	1.6
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	3.4
	X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	1.2
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.1	N/A	Clear Space?	N/A
	Road X Slope (%)	5.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





