

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 23558	Main Street: HAMLIN_PARK_DR	Cross Street: PARK_RD	Location: NW
ADA ID: 7F8FFF784953	Ramp Type: BlendTrans1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



Possible Solutions:

**Remove & Replace Landing.  
Remove & Replace Gutter.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.3, R302.7.2, R304.5.4**

Street 1 Name	<b>PARK RD</b>
Stop Condition-Street 1	<b>None</b>
Street 2 Name	<b>N/A</b>
Stop Condition-Street 2	<b>N/A</b>

Total Cost: \$ **1250.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	<b>97.0</b>	Yes	BlendTrans Slope (%)	<b>3.5</b>
Yes	Ramp Width (in)	<b>48.0</b>	Yes	BlendTrans XSlope (%)	<b>1.5</b>
N/A	Flare Type LT	<b>Sloped</b>	N/A	Flare Type RT	<b>Sloped</b>
N/A	Flare Slope LT (%)	<b>3.5</b>	N/A	Flare Slope RT (%)	<b>6.7</b>
N/A	Flare Traversable LT?	<b>No</b>	N/A	Flare Traversable RT?	<b>No</b>
Yes	Landing Length (in)	<b>70.0</b>	Yes	DWS Provided?	<b>Yes</b>
Yes	Landing Width (in)	<b>48.0</b>	Yes	DWS Contrast?	<b>Yes</b>
Yes	Landing Slope (%)	<b>0.6</b>	Yes	DWS Length (in)	<b>24.0</b>
No	Landing X Slope (%)	<b>2.3</b>	Yes	DWS Full Width?	<b>Yes</b>
N/A	Landing Curb? (Y/N)	<b>Yes</b>	Yes	DWS Offset (in)	<b>0.0</b>
N/A	Shared Landing?	<b>No</b>			
Yes	Gutter Ponding?	<b>No</b>	No	Gutter Slope (%)	<b>6.1</b>
No	Gutter Lip Ht (in)	<b>0.3</b>	Yes	Gutter X Slope (%)	<b>1.3</b>
N/A	Painted X Walk1?	<b>No</b>	N/A	Painted X Walk2?	<b>N/A</b>
	X Walk 1 Direction	<b>To SE</b>		X Walk 2 Direction	<b>N/A</b>
	X Walk 1 Width (in)	<b>N/A</b>		X Walk 2 Width (in)	<b>N/A</b>
	X Walk 1 Slope (%)	<b>3.4</b>		X Walk 2 Slope (%)	<b>N/A</b>
	X Walk 1 X Slope (%)	<b>0.7</b>		X Walk 2 X Slope (%)	<b>N/A</b>
N/A	Ramp inside XWalk1?	<b>N/A</b>	N/A	Ramp inside XWalk2?	<b>N/A</b>
	Road Slope (%)	<b>0.7</b>		Clear Space?	<b>Yes</b>
	Road X Slope (%)	<b>3.4</b>	N/A	Clear Space to XWalk (in)	<b>N/A</b>
Yes	Any Obstructions?	<b>No</b>	Yes	Storm Grate/Utility Hazard?	<b>No</b>
	Obstruction Type			Storm Grate/Utility Type	
		<b>N/A</b>			<b>N/A</b>
			Yes	Surface Condition? (G/P)	<b>Good</b>
			Yes	Curb Slope (%)	<b>2.7</b>

