


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 15864	Main Street: LEROY_ST	Cross Street: ST_JAMES_PL	Location: W
ADA ID: 7F96E15D6992	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 7.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	35.0
	Remove & Replace Gutter.		Yes	Ramp Width (in)	53.5
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	0.6
			N/A	Flare Traversable LT?	Yes
			No	Landing Length (in)	35.5
			Yes	Landing Width (in)	53.5
			No	Landing Slope (%)	3.0
			Yes	Landing X Slope (%)	2.5
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305.1.4, R305.2, R304.5.4</p>			N/A	Flare Type RT	N/A
			Yes	Flare Slope RT (%)	7.7
			N/A	Flare Traversable RT?	Yes
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	25.5
			No	DWS Full Width?	No
			N/A	DWS Offset (in)	9.5
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
<p>Total Cost:</p> <p>\$ 2600.00</p>			Yes	Gutter X Slope (%)	1.6
			N/A	Painted X Walk1?	N/A
				X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	4.8
				X Walk 1 X Slope (%)	2.5
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

