

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44418	Main Str	Main Street: TRAVIS_GULCH_DR			Cross Street: ARDREY_KELL_RD				NE	
ADA ID: 7FA23DF4D018	18 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data	Data Compliance Description			
and the second		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	7.3	
	TRE AND A			No	Ramp Width (in)	45.5	Yes	Ramp XSlope (%)	1.6	
A STATE A STATE	See and			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	-100			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	2 Paris and			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A MARINE			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Person	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
ARDREY L				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	1 1 2 2 3	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
E 6	- + T	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A 10 20			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
5 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	a little second				X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
L de la companya de l				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name TRA	AVIS GULCH DR				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

