

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10024956	Main Street: DISTRICT_SOUTH_DR	Cross Street: N/A	Location: S
ADA ID: 7FB5F09C91F0	Ramp Type: Directional2	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0.25	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305.2

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	82.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	89.0	Yes	Grade Break Slope (%)	4.7
Yes	Ramp Slope (%)	8.1	Yes	Grade Break XSlope (%)	0.6
No	Ramp XSlope (%)	3.4			
N/A	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	92.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	90.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.2	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	1.5	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	14.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	47.5
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.2
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
N/A	Painted X Walk1?	Yes		Road Slope (%)	1.5
	X Walk 1 Direction	To N		Road X Slope (%)	1.1
	X Walk 1 Width (in)	91.0		Clear Space?	Yes
	X Walk 1 Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.1	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	8.4

Total Cost: \$ 1800.00

