

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27288Main Street: PIPER_STATION_DRCross Street: REA_RDLocation:EADA ID: 7FB7E9F680CBRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	REA RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solution	
Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	
Restripe Crosswalk.	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.2.2,	N
R304.5.3	N
	N

Total Cost:	\$ 2050.00

Field Measurements/Component Compliance						
Compl	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	109.0	No	Ramp Slope (%)	11.7	
No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	3.1	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	127.0	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	No	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
Ł.						





